

---

Needed: Estimate \$100 plus add on boot costs.

1. Leather Boots (Prefer Steel or Composite Toe)
2. Jacket, Flame Resistant or Leather (may get welding sleeves)
3. Clear Safety Glasses
4. Shade 5 Safety Glasses for Oxy- Oxy Fuel (Mankato Only)
- 5.