

Job Hazard Analysis

JHA Name: [Stitching & Binding Machine](#)

Check for
Exposure:

1 Impact

2 Penetration or
Cut

X

3 Crush or Pinch

X

4 Chemical or
Harmful Dust

5 Heat

6 Light (optical)
Radiation

7 Electrical
Contact

8 Ergonomic/
Human Factors

Example: Working in cramped spaces, repetitive movements, awkward postures, vibration, heavy lifting, etc. Note: "This category may also include unique hazards presented from tasks that require demanding or challenging degrees of mental and/or physical effort to be exerted by an individual. See *Physical Effort Definition/Examples*

9 Environmental

Job Hazard Analysis

JHA Name: [Stitching & Binding Machine](#)

Assessment Date: 07-10-17

Revision Date: 07-10-17

Building or Location: